Bingham Town Council - Play Area Inspection Report Summary August 2020

Cogley Lane (CrowClose)

Page Item and issue	Action Taken	Completed	Outstanding Work
4 Litter Bin - Split	Taped for safety		Quote for replacement required
5 Seating - Loose	Concreted in place	Yes	
6 General Surface - rotted posts	Timber posts replaced	Yes	
7 Agility Trail - paintwork poor condition	None		Descale and paint required
8 AB Frame - Bolt Loose	Streetwise to weld		Awaiting Quote
10 Multiplay - Graffiti	Repainted to cover	Yes	
11 Multiplay - Rotton Timber	Replaced with Marine Ply	Yes	
12 Rocker Bike - concrete exposed	Matting installed and bark over	Yes	
13 Rocker Horse - concrete exposed	Matting installed and bark over	Yes	
17 Swings - wear in bushes	One Toddler and One Junior swing in place		Rewelding required
18 Swings - chain wear	Streetwise checked - monitor not replace	Yes	
18 Swings - replace missing swings	Only 2 swings for social distancing		Rewelding required

Wychwood Road

Remains closed due to matting shrinkage concerns and re-fit in August. Bin removed and placed at combination goal area Swings removed for use elsewhere, AB Frame rope and metal fencing to be removed as work commences for use elsewhere. Quote for combination goal surface area received. Other quotations to be obtained.

Wallenfells

Page	Item and issue	Action Taken	Completed	Outstanding Work
4	Gate - adjust	Adjustments made		Needs post re-setting
5	Gate - adjust	Adjustments made		Needs post re-setting
7	Butterfly Rocker - algae	Cleaned	Yes	
8	Rotator - rub down edges and treat	Sanded and treated	Yes	
9	Swings - Chain Wear	Streetwise checked - monitor	Yes	
10	Gullwing Seesaw - pivot bolts loose	Streetwise to weld		Awaiting quote
11	Basket Swing - Shackles tight	Shackles loosened	Yes	
12	Basket Swing - secondary device	Not fitted at manufacture		Referring to manufacturer
13	Climber Rope - excessive movement	Tightened	Yes	
		Needs repair and removed for social		
14	Basket Swing - replace	distancing		Quote needed
15	Climbing wall - scratched	Streetwise informed monitor, laminate ok	Yes	

Orchard Park	

Page	Item and issue	Action Taken	Completed	Outstanding Work
21	Log frame - eye bolts loose	Adjustments made		Spoken with Proludic - washers

Separate to ROSPA report the bench in the toddler area is loose and a post on the log stack. Proludic have inspected these items. The loose eye bolts were discussed on site as will easily come loose again, the ground staff suggested a washer and proludic are investigating this. There are issues with the surfacing with a black residue coming off onto shoes and staining shoes and the green wet pour faces and equipment. Proludic are investigating.